

PROFORMA REGARDING BUILDING SAFETY

CERTIFICATE

No. _____

Date : 20/6/2023

It is certified that an inspection team headed by Mr. Prasanna J. Bawale (Diploma Civil Engineer) (Name of Officers with designation) from Kolhapur Municipal Corporation (Name of Department / Office) inspected the Kolhapur Public School, R.N.Kop (Name and Address of the school) on 19/06/2023 and found that the Kolhapur Public School (Name of school) building is structurally sound & stable, & its stability will not be endangered by its use for which purpose it is constructed. The entire structure of the school building is safe enough and intact as per the norms prescribed by the Central / State / U. T. Govt.

The above valid for a period of One Year



Signature with seal : _____

Name : _____

Designation : _____

PRASANNA J. BAWALE
PRASANNA J. BAWALE
Diploma Civil Engineer
2484, C Ward, Shaniwar Peth
Kolhapur. Mo.9921362697

To

R.L.TAWDE FOUNDATION'S

KOLHAPUR PUBLIC SCHOOL

RS 576 NEAR RAJENDRA NAGAR WATER TANK,

RAJENDRA NAGAR KOLHAPUR 416008

(Name and Address of the Institution)

