

PROFORMA REGARDING BUILDING SAFETY

CERTIFICATE

No. _____

Date : 14/07/2021

It is certified that an inspection team headed by Mr. Prasanna J. Bawale (Diploma Civil Engineer) (Name of Officers with designation) from Kolhapur Municipal Corporation (Name of Department / Office) inspected the KOLHAPUR PUBLIC SCHOOL, RS 576 NEAR RAJENDRA NAGAR WATER TANK, RAJENDRA NAGAR KOLHAPUR 416008 (Name and Address of the school) on _____ and found that the KOLHAPUR PUBLIC SCHOOL (Name of school) building is structurally sound & stable, & its stability will not be endangered by its use for which purpose it is constructed. The entire structure of the school building is safe enough and intact as per the norms prescribed by the Central / State / U. T. Govt.

The above valid for a period of One Year

PRASANNA
PRASANNA J. BAWALE
Diploma Civil Engineer
2084, C Ward, Shanwar Path
Kolhapur. Mo.9921762697



Signature with seal : _____

Name : _____

Designation : _____

To

R.L.TAWDE FOUNDATION'S
KOLHAPUR PUBLIC SCHOOL

मनिष अग्नि
सहा. न. र. ३५ श. र.
कोल्हापूर महानगरपालिका

RS 576 NEAR RAJENDRA NAGAR WATER TANK,
RAJENDRA NAGAR KOLHAPUR 416008

(Name and Address of the Institution)

